



6929 N. Lakewood Avenue  
Tulsa, OK 74117

**SHORT TERM PUBLIC NOTICE UNDER RULE 51.333(a)**

August 25, 2020

**Carrier:** Verizon New York Inc., 140 West Street, New York, NY 10007

**Contact:** For additional information on these planned network changes, please contact:

Marcia Chaffin  
Verizon Network Engineering  
385 Myles Standish Blvd.  
Taunton, MA 02780  
978-552-3638

John Dunne  
Manager – Global Engineering and System Performance  
Verizon Wireline Network Operations  
999 W Main St., 04 FLR, Freehold, NJ USA 07728  
732-683-5126

**Implementation Date:** On or after February 1, 2021

**Planned Network Change(s) will occur at the following location(s) in New York:**

Verizon Central Office	Address	CLLI
South Dayton NY DMS10 switch	416 Pine Street South Dayton, NY 14138	<b>SDTNNYPIDS0</b>
Buffalo NY Packet End Office switch	65 Franklin Street Buffalo, NY 14202	<b>BFLONYFRPS0</b>

This notice may also be viewed at <http://www.verizon.com/about/terms-conditions/network-disclosures>

PLEASE NOTE:

- All references to the South Dayton NY DMS10 switch are associated with CLI code SDTNNYPIDS0 and will not be repeated throughout this notice.
- All references to the Buffalo NY Packet End Office (PEO) switch are associated with CLI code BFLONYFRPS0 and will not be repeated throughout this notice.

**Description of the Planned Network Change(s):**

The Verizon South Dayton NY DMS10 switch, located at 416 Pine Street, South Dayton, NY 14138, will be retired and removed from the network after all traffic served by this switch is migrated to the Verizon Buffalo NY PEO switch, located at 65 Franklin Street, Buffalo, NY 14202. All traffic to be migrated includes, but is not limited to, Inter-LATA (ACCESS/FG-B-D/CLEC/IXC), wireless, and paging traffic.

**Description of Reasonably Foreseeable Impact(s) of the Planned Change(s):**

Competitive local exchange carriers (CLECs), interexchange carriers (IXCs, IECs), wireless carriers, and paging carriers will need to secure new trunk groups built to the Buffalo NY PEO switch or have existing trunk groups to that switch augmented. Carriers that are code holders for access connectivity in the South Dayton NY DMS10 switch will be required to reposition the codes to the Buffalo NY PEO switch.

All ASRs for the Buffalo NY PEO switch must be received no later than December 15, 2020 in order to provide sufficient time to migrate the traffic described above. These direct end office trunk (DEOT) interconnections will support traffic migration for the South Dayton NY DMS10 switch prior to its eventual decommissioning. Local Exchange Routing Guide (LERG) change effective dates will be posted prior to decommissioning of the South Dayton NY DMS10 switch (**on or after February 1, 2021**). This will serve to guide interconnect re-routes of traffic for the one (1) native code currently served by the South Dayton NY DMS10 switch to reflect the Buffalo NY PEO switch as the new home switch. All ASRs for the Buffalo NY PEO switch must carry the project code of SDTNNYPIDS0.